

Response To Non-Ductile Columns Survey; Status as at 29/5/2020

SR number	Address	Building name	Status	Comment
437122	72 ABEL SMITH STREET		Resolved	S. Owner advises building is Out Of Scope/Not Applicable To This Two Storey Building. Building is joined to 84 Abel Smith Street.
437123	84 ABEL SMITH STREET		Confirmed	S. Owners engineer advises building has been strengthened to 67%NBS and lowest performing non-ductile column after the strengthening scores 67%NBS(IL2) at time of assessment.
437139	121 ADELAIDE ROAD		Confirmed	S. Owners engineer advises columns have been assessed and found to score >100%NBS(IL2) at time of assessment. Owners engineer advises building has been strengthened to 67%NBS.
437096	11 BOLTON STREET		Possible	S. No response received to survey
437153	80 BOULCOTT STREET	Bldg - A	Possible	S. No response received to survey
440833	84 BOULCOTT STREET	Bldg - B	Possible	S. No response received to survey
437120	31 BOULCOTT STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score 100%NBS (IL2) at time of assessment.
437101	39 BOULCOTT STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score at least 67%NBS(IL2) at time of assessment.
437105	1 BOWEN STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score 34-66%NBS(IL2) at time of assessment.
437093	84 CABLE STREET		Possible	S. No response received to survey
437091	55 CABLE STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score at least 34%NBS(IL3) at time of assessment but they have not determined a final %NBS.
437094	11 CHURCH STREET		Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS3101:1982
437097	97 COURTENAY PLACE		Confirmed	S. Owners engineer advises columns have been assessed and found to score 80-99%NBS(IL2) at time of assessment.
437098	148 CUBA STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score 34-66%NBS(IL2) at time of assessment.
437125	202 CUBA STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score 80-99%NBS(IL2) at time of assessment.
437100	99 CUSTOMHOUSE QUAY		Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS: 3101:1982
437099	36 CUSTOMHOUSE QUAY		Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS3101:1982
435874	5 EVA STREET	Bldg - B	Confirmed	S. Engineering firm no longer exists so cannot complete survey. Original assessment identified building as having non-ductile columns with later assessment by another engineering firm identifying building as not earthquake-prone.
437102	126 FEATHERSTON STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score 57%NBS(IL2) at time of assessment.
434882	2 GILMER TERRACE	Bldg - B	Possible	S. No response received to survey
436068	2 GILMER TERRACE	Bldg - C	Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS:3101:1982
439066	8 GILMER TERRACE		Confirmed	S. Owners engineer advises columns have been assessed and found to score 100%NBS(IL2) at time of assessment. Owners engineer advises building has been strengthened to 100%NBS(IL2).
437103	5 GILMER TERRACE		Confirmed	S. Owners engineer advises columns have been assessed and found to score 80-99%NBS(IL2) at time of assessment.
437138	25 HAINING STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score 80-99%NBS(IL2) at time of assessment. Owners engineer advises buildings overall %NBS is lower than that of the columns.
437104	22 HAWKESTONE STREET		Resolved	S. Engineering firm no longer exists so cannot complete survey. Owners engineer letter advises 'all columns have been detailed for ductility'.
437140	44 HILL STREET		Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS: 3101:1982
437131	93 LAMBTON QUAY		Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS: 3101:1982
437049	218 LAMBTON QUAY		Confirmed	S. Owners engineer advises columns have been assessed and found to score >100%NBS(IL2) at time of assessment.
437024	157 LAMBTON QUAY	Bldg - A	Confirmed	S. Owners engineer advises columns have been assessed and found to score 80-99%NBS(IL2) at time asssd. Owners engineer advises buildings overall %NBS is lower than that of the columns. Owners engineer advises building has been strengthened to 80%NBS(IL2).
437152	13 MANNERS STREET		Possible	S. Engineering firm no longer exists so cannot complete survey. If non-ductile columns are present, engineers report and peer review indicate these achieve at least 34%NBS.
437108	76 MANNERS STREET		Possible	S. No response received to survey
437107	2 MANNERS STREET		Resolved	S. Owners engineer advises the building did contain columns that were designed as non-seismic or limited ductile but all of these columns have been strengthened such that their equivalent reinforcement confinement has been resolved. Bldg Strngth to 67%NBS.
437106	18 MANNERS STREET		Resolved	S. Owners engineer advises the building did contain columns that were designed as non-seismic or limited ductile but all of these columns have been strengthened such that their equivalent reinforcement confinement has been resolved. Bldg Strngth to 80%NBS.
436562	10 MARION STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score 100%NBS(IL2) at time of assessment. Owners engineer advises buildings overall %NBS is lower than that of the columns.
437109	81 MOLESWORTH STREET		Resolved	S. Owner advises the building did contain columns that were designed as non-seismic or limited ductile but all of these columns have been strengthened such that their equivalent reinforcement confinement has been resolved. Bldg Strngth to 100%NBS(IL2).
437110	2 MOWBRAY STREET		Confirmed	S. Engineering firm no longer exists so cannot complete survey. Report received from council contracted engineer confirms building contains non-ductile columns. Building is not earthquake-prone after strengthening work completed.

SR number	Address	Building name	Status	Comment
437142	326 ORIENTAL PARADE		Confirmed	S. Owners engineer advises columns capacity has not been assessed yet.
437111	260 ORIENTAL PARADE		Confirmed	S. Owners engineer advises columns have been assessed and found to score 80-99%NBS(IL2) at time of assessment.
437143	4 OXFORD TERRACE		Confirmed	S. Owners engineer advises columns have been assessed and found to score at least 34%NBS(IL2) but have not determined a final %NBS score for the columns. Owners engineer advises the buildings overall %NBS is lower than the %NBS of the columns.
437112	49 PIPITEA STREET		Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS3101:1982
437144	49 RIDDIFORD STREET	Bldg - 24	Resolved	S. Owners engineer advises the building did contain columns that were designed as non-seismic or limited ductile but all of these columns have been strengthened such that their equivalent reinforcement confinement has been resolved. Bldg Strngth to 100%NBS.
437113	9 STOUT STREET		Confirmed	S. Owner advises the columns have been assessed and found to score at least 34%NBS(IL2) at time of assessment but they have not determined a final %NBS.
437114	79 TARANAKI STREET		Possible	S. No response recieved to survey
437806	190 TARANAKI STREET		Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS3101:1982. Owner engineer advises building has been strengthened to 70%NBS(IL2)
439170	50 THE TERRACE		Resolved	S. Engineering firm no longer exists so cannot complete survey. Owners engineer letter advises 'all columns have been detailed for ductility.'
437129	80 THE TERRACE		Possible	S. No response received to survey
437145	345 THE TERRACE		Possible	S. No response received to survey
437685	54 THE TERRACE		Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS3101:1982. Owner engineer advises building has been strengthened to 80%NBS(IL2)
437118	44 THE TERRACE		Confirmed	S. Owners engineer advises columns have been assessed and found to score >100%NBS(IL2) at time of assessment. Owners engineer advises building has been strengthened to 85%NBS.
437117	139 THE TERRACE		Confirmed	S. Owners engineer advises columns have been assessed and found to score 100%NBS (IL2) at time of assessment.
437154	133 THE TERRACE		Confirmed	S. Owners engineer advises columns have been assessed and found to score 80-99%NBS(IL2) at time of assessment. Owners engineer advises buildings overall %NBS is lower than that of the columns.
437116	138 THE TERRACE		Resolved	S. Owners engineer advises the building did contain columns that were designed as non-seismic or limited ductile but all of these columns have been strengthened such that their equivalent reinforcement confinement has been resolved. Bldg Strngth to 67%NBS.
437115	88 THE TERRACE		Resolved	S. Owners engineer advises the building did contain columns that were designed as non-seismic or limited ductile but all of these columns have been strengthened such that their equivalent reinforcement confinement has been resolved. Bldg Strngth to 70%NBS.
437146	169 TORY STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score at least 34%NBS(IL3) at time of assessment but they have not determined a final %NBS.
437137	130 VICTORIA STREET		Confirmed	S. Owner advises columns have been assessed and found to score 80-99%NBS(IL2) at time of assessment.
434143	125 VICTORIA STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score >100%NBS(IL2) at time of assessment. Owners engineer advises building has been strengthened to 80%NBS.
437148	118 VICTORIA STREET		Possible	S. Owners Rep refused to provide survey response.
437149	25 VIVIAN STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score >100%NBS(IL2) at time of assessment. Owners engineer advises buildings overall %NBS is lower than that of the columns.
437036	142 WAKEFIELD STREET	Bldg - A	Confirmed	S. Owners engineer advise the columns have been assessed and found to score at least 34%NBS(IL2) at time of assessment but they have not determined a final %NBS. Building remains closed after 2016 earthquake.
437042	142 WAKEFIELD STREET	Bldg - B	Confirmed	S. Owners engineer advise the columns have been assessed and found to score at least 34%NBS(IL2) at time of assessment but they have not determined a final %NBS. Building remains closed after 2016 earthquake.
436835	150 WAKEFIELD STREET	Bldg B; James Smith Car Park Building	Confirmed	S. Owners engineer advises columns capacity has not been assessed. Building remains empty after 2016 earthquake.
436834	162 WAKEFIELD STREET	Bldg A; Amora Hotel	Confirmed	S. Owners engineer advises columns have been assessed and found to score <34%NBS (IL2). Owners engineer advises buildings overall %NBS is lower than that of the columns. Building is vacant.
436832	101 WAKEFIELD STREET	Bldg - C - Civic Administration Building	Confirmed	S. Owners engineer advises columns have been assessed and found to score at least 34%NBS(IL3) at time of assessment but they have not determined a final %NBS. Building remains empty after 2016 earthquake.
437124	15 WALTER STREET		Confirmed	S. Owners engineer advises columns have been assessed and found to score >100%NBS(IL2) at time of assessment. Owners engineer advises building has been strengthened to 100%NBS(IL2)
437150	10 WASHINGTON AVENUE		Confirmed	S. Owners engineer advises columns have been assessed and found to score at least 75%NBS at time of assessment.
437121	5 WILLESTON STREET		Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS3101:1982.
437119	15 WILLESTON STREET		Possible	S. Owners Rep refused to provide survey response.
437090	8 WILLIS STREET		Resolved	S. Owners engineer advise the building does not contain columns designed as non-seismic or limited ductile in accordance with NZS3101:1982
437088	159 WILLIS STREET	Bldg - A	Confirmed	S. Owners engineer advises columns have been assessed and found to score 80-99%NBS(IL2) at time of assessment.
437126	159 WILLIS STREET	Bldg - B	Confirmed	S. Owners engineer advises columns have been assessed and found to score 80-99%NBS(IL2) at time of assessment.
436958	88 WILLIS STREET	Bldg - A	Confirmed	S. Owners engineer advises columns have been assessed and found to score 80-99%NBS(IL2) at time of assessment. Owners engineer advises building has been strengthened to 85%NBS(IL2).